ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0685	NA	VINAYAKA LAYOUT Srinivaspura Village
Segment No.	**Total Length (m)**	
5/S-W0685/S123024	246.64	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	246.64	77.624430	13.103243	77.625023	13.105395	RI-A07	SWD

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Providing Asphalting to Roads & Drains and at Srinivaspura Village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	2000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Providing Asphalting to Roads & Drains and at Srinivaspura Village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	005-15-000010
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/213/2014-15	14/01/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
14/01/2015	13/01/2015	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
S.K.KESHAVAMURTHY		0.00
Phone No.	**E-Mail ID**	
9902126909		

Field Inspection Details

Number of Trees	Any Other Information	Name
21		CHANDRAKANTHA

Date of Inspection	Remarks
19/07/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/07/2016	18/08/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0685

SE	VASU K M	19/07/2016	18/08/2016	COMPLETED
EE	YARAPPA REDDY	19/07/2016	18/08/2016	COMPLETED
AEE	J N LOKESH	19/07/2016	18/08/2016	COMPLETED
AE	CHANDRAKANTH	19/07/2016	18/08/2016	COMPLETED
AE	CHANDRAKANTH	19/07/2016	18/08/2016	COMPLETED